

Aviation House - Condition Assessment

Published on Freyssinet NZ Ltd (<https://www.freyssinet.co.nz>)

[Aviation House - Condition Assessment](#)

Aviation House - Condition Assessment

Published on Freyssinet NZ Ltd (<https://www.freyssinet.co.nz>)



Aviation House - Condition Assessment

Published on Freyssinet NZ Ltd (<https://www.freyssinet.co.nz>)

Client: Keyway Construction

Date: July, 2019

Type: Design and Construct

Location: Wellington

New Zealand

The project was a seven storey building in the Wellington CBD. The building was not up to the current NBS standard. Drawings showed it was designed and potentially constructed in 1930-1940. Freyssinet were engaged to undertake a condition assessment of the building, with the aim to establish the current baseline condition which could then be fed into a remediation strategy, pending the findings of the condition assessment.